

NHTSA Consumer Complaints as of May 23, 2014

15 10272382 GMC YUKON 2007 LATCHES/LOCKS/
LINKAGES:DOORS:LATCH TL*THE CONTACT OWNS A 2007 GMC YUKON.
SINCE FEBRUARY OF 2009, THE CHROME PLATED INTERIOR DOOR HANDLES
HAVE BEEN PEELING. THE VEHICLE WAS TAKEN TO THE REPAIR SHOP IN
MARCH OF 2009 AND THE MECHANIC STATED THAT THE WARRANTY WAS
EXPIRED; THEREFORE, THE CONTACT WOULD HAVE TO PAY FOR THE REPAIR.
THE VIN WAS UNKNOWN. THE CONTACT FEELS THAT THIS IS A
MANUFACTURER DEFECT. THE FAILURE MILEAGE WAS 46,000.

BELLEVILLE MI 20090515

15 10273673 GMC YUKON 2007 LATCHES/LOCKS/LINKAGES I
HAVE JUST PURCHASED A USED 2007 YUKON SLT, ON A DAILY BASIS MY
FAMILY AND I EXPERIENCE SMALL CUTS ON OUR HANDS AND FINGERS, BY
OPENING THE INTERIOR CAR DOORS. THE LATCHES BECOME EXTREMELY
SHARP AT THE TOP SEEMS. I HAVE HAD TO TEACH MY CHILDREN HOW TO
AVOID GETTING CUTS. I HAVE HAD THE CAR FOR FIVE DAYS AND WE HAVE
SUSTAINED CUTS FOR FIVE DAYS. HOW LONG SHOULD THIS GO ON??

*TR INDIANAPOLIS IN 20090608

15 10352764 GMC YUKON 2007 LATCHES/LOCKS/
LINKAGES:DOORS:LATCH TL*THE CONTACT OWNS A 2007 GMC YUKON.
THE PASSENGER SIDE DOOR HANDLE WAS BROKEN AND WHENEVER THE
DOOR WAS OPENED THE PASSENGER SUSTAINED CUTS AND BRUISES ALL
OVER THEIR HANDS. THE DOOR HANDLE ALSO CUT THE PASSENGERS HAND
WHEN THEY ENTERED THE VEHICLE. THE VEHICLE WAS TAKEN TO THE
DEALER WHO STATED THEY WOULD REPLACE THE DOOR HANDLE AT HER
EXPENSE FOR THE LABOR COST OF \$139. THE MANUFACTURER WAS CALLED
AND SHE WAS NOT GETTING A FAVORABLE ANSWER FROM THE
REPRESENTATIVE THAT SHE SPOKE WITH. THE FAILURE MILEAGE WAS
49,473. NORTHPORT FL 20100824

15 10361028 GMC YUKON 2007 LATCHES/LOCKS/LINKAGES 2007
GMC YUKON. INTERIOR DOOR HANDLES. CHROME PLATING HAS SEPARATED
FROM THE TOP WHERE HANDLE IS GRABBED. HANDLES ARE RAZOR SHARP

NHTSA Consumer Complaints as of May 23, 2014

AND CARE IS NEEDED WHEN OPENING DOOR OTHERWISE INJURY CAN AND
HAS OCCURRED. *TR GANADO TX 20101016

15 10370447 GMC YUKON 2007 LATCHES/LOCKS/LINKAGES I OWN
A 2007 GMC YUKON XL AND THE PASSENGER AND DRIVER DOOR CHROME
HANDLE IS PEELING OFF AND I GOT MY FINGER CUT AS I TRIED TO EXIT ON
THE DRIVER SIDE DOOR A COUPLE OF TIMES . I JUST PUT TAPE AROUND IT
BUT I THINK THAT IT SHOULD BE FIXED IT'S A HAZARD AND DANGER TO HAVE
THAT HAPPENED. *TR SAN PABLO CA 20101104

15 10379791 GMC YUKON 2007 LATCHES/LOCKS/LINKAGES THE
CHROME METAL COVERING THE INSIDE DOOR HANDLES OF MY YUKON HAS
CRACKED AND IS SEPARATING FROM THE HANDLES. THE SHARP CHROME
METAL INJURED MY WIFE BY SLICING HER FINGER AS SHE EXITED THE
VEHICLE. MY DAUGHTER PREVIOUSLY RAN HER FOOT ON THE BACK SEAT
HANDLE AND CUT HER FOOT. THIS IS AN OBVIOUS MATERIAL DEFECT AND
SHOULD BE REPLACED. THIS IS DANGEROUS. *TR PEARLAND
TX 20110110

15 10456926 GMC YUKON 2007 LATCHES/LOCKS/LINKAGES
DASHBOARD HAS CRACKED SIGNIFICANTLY IN TWO LOCATIONS ONE OF
WHICH IS BY THE FRONT PASSENGER AIRBAG. ALSO, THE INTERIOR AND
EXTERIOR DOOR HANDLES HAVE PEELED AND CRACKED. SPECIFICALLY, THE
INTERIOR HANDLES HAVE PEELED TO THE POINT OF CAUSING DAMAGE TO
THE DRIVER/PASSENGER HANDS UPON USAGE. *JS
BERGHEIM TX 20110126