

NHTSA Consumer Complaints as of October 18, 2015

13 10767427 2006 HONDA ACCORD Air Bags I RECEIVED 2 RECALL NOTICES FROM HONDA IN THE PAST YEAR AND I CONTACTED LOCAL HONDA DEALER. THEY SAID THEY DON'T HAVE THE PARTS FOR FIXING MY PROBLEM. THEY SAID THEY WILL LET ME KNOW ONCE THEY HAVE THE PARTS. AFTER A COUPLE OF MONTHS I CALLED AGAIN AND THEY SAID THEY DON'T HAVE THE PARTS. THEY SAID I CAN FILE A COMPLAINT. THE DEALER I CONTACTED : GOUDY HONDA, 1400 W MAIN ST, ALHAMBRA, CA 91801 TEMPLE CITY CA Failure Date: 09/22/2015

13 10778495 2006 HONDA ACCORD Air Bags WAS INVOLVED IN CAR ACCIDENT, CAR LOSS CONTROL IN LEFT LANE, SPUN 720 DEGREES INTO RIGHT SHOULDER, SPUN ANOTHER 720 DEGREES, AND THEN 5 BARREL ROLLS DOWN ON THE RIGHT SHOULDER ON THE 101 STATE FREEWAY CA HEADING NORTHBOUND TO SAN FRAN BAY AREA NEAR KING CITY, CA. DRIVER AND PASSENGER AIR BAGS DID NOT DEPLOY GOLETA CA Failure Date: 09/17/2015

13 10766392 2006 HONDA ACCORD Air Bags WHILE WAITING TO HAVE OUR AIRBAG RECALL DONE THE SSR LIGHT CONTINUED TO GO OFF AND ON . WE THOUGHT IT WAS DUE TO THE AIRBAG RECALL ON THE VEHICLE . AFTER THE RECALL WAS DONE , THE SSR LIGHT CONTINUE TO STAY ON . THE SERVICE DEPARTMENT AT HONDA SAID IT WAS THE AIRBAG SENSOR IN THE SEAT THAT NEEDED TO BE REPLACED. IT WOULD COST \$290.00 TO FIX THIS. I INVESTIGATED ONLINE AND FOUND MANY ISSUES WITH THE AIRBAG SENSOR THAT DID HAVE RECALLS ON THEM. THE 2006 HONDA ACCORD WAS NOT LISTED FOR A RECALL FOR THIS ISSUE BUT, FOUND MANY CUSTOMERS WITH COMPLAINTS WITH THIS SAME ISSUE. ON NHTSA REPORTS THEY HAD A ARTICLE STATING HONDA RECALLS 81,000.00 ACCORDS OVER AIRBAG SENSOR. THEY WERE RECALLING 2004-05 ACCORD SEDANS. THEY NEED TO EXTEND THIS TO 2006 VEHICLES. BURLINGTON MA Failure Date: 09/12/2015

13 10759124 2006 HONDA ACCORD Air Bags AFTER A 3 MONTH WAIT BACK IN 2014, MY DRIVER SIDE AIRBAG WAS FINALLY REPLACED ON

NHTSA Consumer Complaints as of October 18, 2015

1/12/15 BY CORAL SPRINGS AUTOMALL HONDA'S SERVICE DEPARTMENT. A MONTH AGO I GET ANOTHER RECALL NOTICE ON THE AIRBAG AND SORT OF SKIM OVER IT THINKING I JUST GOT IT REPLACED. I WAS JUST DOUBLE CHECKING THAT ALL SAFETY RECALLS HAD BEEN DONE ON THE CAR WHEN I REALIZED THAT THIS LAST RECALL WAS FOR THE PASSENGER SIDE AIR BAG. THE DEALER SHIP ONLY REPLACED THE INFLATOR ON THE DRIVER SIDE. I CAN ONLY IMAGINE HOW MANY PEOPLE ALSO ARE IN THE SAME BOAT NOT REALIZING HONDA DID NOT BOTHER REPLACING BOTH FRONT SIDE AIR BAGS AND SEEING THIS SECOND NOTICE THAT IT WAS ALREADY FIXED. THERE ARE MANY AVENUES TO ADDRESS THIS AND WOULD LIKE TO SEE THE NHTSA MAKE A NEWS RELEASE ADDRESSING THIS VERY ISSUE FOR ALL CAR OWNERS - SPECIFICALLY THAT BOTH AIRBAGS NEED TO BE REPLACED AND THAT IF YOU PREVIOUSLY TOOK YOUR CAR IN, DEALERSHIPS DID NOT BOTHER TO REPLACE BOTH. PARKLAND, FL Failure Date: 08/25/2015

13 10735112 2006 HONDA ACCORD Air Bags TL* THE CONTACT OWNS A 2006 HONDA ACCORD. THE CONTACT RECEIVED NOTIFICATION OF NHTSA CAMPAIGN NUMBER: 15V370000 (AIR BAGS); HOWEVER, THE PART NEEDED TO REPAIR THE VEHICLE WAS UNAVAILABLE. THE CONTACT STATED THAT THE MANUFACTURER EXCEEDED A REASONABLE AMOUNT OF TIME FOR THE RECALL REPAIR. THE MANUFACTURER WAS NOT NOTIFIED OF THE ISSUE. THE CONTACT HAD NOT EXPERIENCED A FAILURE.

440-888-3530 OH Failure Date: 07/20/2015

13 10750331 2006 HONDA ACCORD Air Bags TL* THE CONTACT OWNS A 2006 HONDA ACCORD. THE CONTACT STATED THAT THE VIN WAS INCLUDED IN NHTSA CAMPAIGN NUMBERS: 15V320000 (AIR BAGS) AND 15V370000 (AIR BAGS). BEFORE THE RECALL REPAIRS WERE COMPLETED, THE VEHICLE WAS INVOLVED IN A CRASH. WHILE TRAVELING APPROXIMATELY 25 MPH, ANOTHER VEHICLE CRASHED INTO THE FRONT PASSENGER SIDE OF THE CONTACT'S VEHICLE. NONE OF THE AIR BAGS DEPLOYED. THE VEHICLE WAS TAKEN TO A REPAIR SHOP, BUT THERE WAS NO INVESTIGATION TO DETERMINE WHY THE AIR BAGS DID NOT DEPLOY. THE DEALER WAS NOTIFIED OF THE

NHTSA Consumer Complaints as of October 18, 2015

CRASH AND WAS WAITING FOR THE APPROVAL FROM THE MANUFACTURER TO COMPLETE THE TWO AIR BAG RECALL REPAIRS. THE DRIVER WAS UNINJURED AND A POLICE REPORT WAS FILED. THE FAILURE MILEAGE WAS NOT AVAILABLE. ROCKLAND CA Failure Date: 07/20/2015

13 10734557 2006 HONDA ACCORD Air Bags TL* THE CONTACT OWNS A 2006 HONDA ACCORD. WHILE DRIVING AT A LOW SPEED, THE CONTACT HEARD AN ABNORMAL NOISE COMING FROM THE STEERING. THE CONTACT CRASHED INTO THE REAR OF THE PRECEDING VEHICLE. THE DRIVER SIDE AIR BAG DEPLOYED AND SMOKE EMITTED FROM THE AIR BAG. THE CONTACT SUSTAINED NECK BRUISES AND CHEST INJURIES THAT REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS FILED. THE VEHICLE WAS NOT DIAGNOSED OR REPAIRED. THE MANUFACTURER WAS NOT NOTIFIED OF THE FAILURE. THE VIN WAS INCLUDED IN NHTSA CAMPAIGN NUMBERS: 15V320000 (AIR BAGS) AND 15V370000 (AIR BAGS). THE FAILURE MILEAGE WAS 87,000. MORRIS PLAINS NJ Failure Date: 07/16/2015

13 10734018 2006 HONDA ACCORD Air Bags TL* THE CONTACT OWNS A 2006 HONDA ACCORD. THE CONTACT RECEIVED NOTIFICATION OF NHTSA CAMPAIGN NUMBERS: 15V370000 (AIR BAGS) AND 15V320000 (AIR BAGS). THE PART NEEDED WAS NOT AVAILABLE WITHIN A REASONABLE TIMEFRAME TO SCHEDULE THE RECALL REPAIR. THE DEALER DID NOT GIVE A SPECIFIC DATE FOR WHEN THE PART WOULD BECOME AVAILABLE. THE MANUFACTURER COULD NOT PROVIDE AN ESTIMATED DATE FOR WHEN THE VEHICLE WOULD RECEIVE THE RECALL REPAIR. THE CONTACT HAD NOT EXPERIENCED A FAILURE. WEST LIBERTY OH Failure Date: 07/14/2015

13 10734228 2006 HONDA ACCORD Air Bags TL* THE CONTACT OWNS A 2006 HONDA ACCORD. THE CONTACT RECEIVED NOTIFICATION OF NHTSA CAMPAIGN NUMBER: 15V370000 (AIR BAGS); HOWEVER, THE PART NEEDED TO DO THE REPAIR WAS UNAVAILABLE. THE CONTACT STATED THAT THE MANUFACTURER EXCEEDED A REASONABLE AMOUNT OF TIME FOR THE RECALL REPAIR. THE MANUFACTURER WAS MADE AWARE OF THE ISSUE. THE

NHTSA Consumer Complaints as of October 18, 2015

CONTACT HAD NOT EXPERIENCED A FAILURE. 9502 ELK HILL CT
KY Failure Date: 06/15/2015

13 10723041 2006 HONDA ACCORD Air Bags PLEASE LET ME
KNOW IF THERE HAS BEEN AN AIRBAG RECALL ON THE ABOVE CAPTIONED
VEHICLE. I HAVE HAD NO ACCIDENTS. JUST PUT THE DATE IN ABOVE
BECAUSE IT WAS REQUIRED. THANK YOU. WEST ORANGE NJ
Failure Date: 06/02/2015

13 10732287 2006 HONDA ACCORD Air Bags TL* THE CONTACT
OWNS A 2006 HONDA ACCORD. THE CONTACT RECEIVED A RECALL LETTER
FOR NHTSA CAMPAIGN NUMBER: 15V320000 (AIR BAGS); HOWEVER, THE PART
TO DO THE REPAIR WAS UNAVAILABLE. THE CONTACT STATED THAT THE
MANUFACTURER EXCEEDED A REASONABLE AMOUNT OF TIME FOR THE
RECALL REPAIR. THE MANUFACTURER WAS NOT MADE AWARE OF THE ISSUE.
THE VIN WAS UNAVAILABLE. THE CONTACT HAD NOT EXPERIENCED A FAILURE.
MATTHEWS NC Failure Date: 05/27/2015

13 10716430 2006 HONDA ACCORD Air Bags TL* THE CONTACT
OWNS A 2006 HONDA ACCORD. THE CONTACT RECEIVED A NOTICE FOR NHTSA
CAMPAIGN NUMBER: 14V351000 (AIR BAGS) IN JANUARY; HOWEVER, THE PART
TO DO THE REPAIR WAS NOT AVAILABLE. THE CONTACT SPOKE WITH THE
MANUFACTURER AND WAS INFORMED THAT THERE WAS NO TIME FRAME FOR
THE PART TO BE AVAILABLE. THE CONTACT FELT THE MANUFACTURER
EXCEEDED A REASONABLE AMOUNT OF TIME FOR THE REPAIR. THE CONTACT
HAD NOT EXPERIENCED A FAILURE. UPDATED 7/9/15*CN
CHAMPION MI Failure Date: 05/14/2015

13 10745655 2006 HONDA ACCORD Air Bags I STARTED THE
CAR AND RECEIVED A MESSAGE THAT THE PASSENGER AIRBAG WAS NOT
WORKING. I TOOK IT TO MY MECHANIC AND HE REPAIRED IT FOR ME AT A
COST OF APPROXIMATELY \$400.00(TO THE BEST OF MY RECOLLECTION).
SYCAMORE IL Failure Date: 04/23/2015

NHTSA Consumer Complaints as of October 18, 2015

13 10706336 2006 HONDA ACCORD Air Bags TL* THE CONTACT OWNS A 2006 HONDA ACCORD. THE CONTACT RECEIVED NOTIFICATION OF NHTSA CAMPAIGN NUMBER: 14V351000 (AIR BAGS); HOWEVER, THE PART NEEDED TO DO THE REPAIR WAS NOT AVAILABLE. THE CONTACT BELIEVED THAT THE MANUFACTURER EXCEEDED A REASONABLE AMOUNT OF TIME FOR THE RECALL REPAIR. THE MANUFACTURER WAS CONTACTED AND THERE WERE UNABLE TO PROVIDE A TIME FRAME FOR THE PARTS TO BECOME AVAILABLE. THE CONTACT HAD NOT EXPERIENCED A FAILURE. THE VIN WAS NOT AVAILABLE. ATHENS GA Failure Date: 04/13/2015

13 10702041 2006 HONDA ACCORD Air Bags TL* THE CONTACT OWNS A 2006 HONDA ACCORD. THE CONTACT RECEIVED NOTIFICATION OF NHTSA CAMPAIGN NUMBER: 14V351000 (AIR BAGS) HOWEVER, THE PART TO DO THE REPAIR WAS UNAVAILABLE. THE CONTACT STATED THAT THE MANUFACTURER EXCEEDED A REASONABLE AMOUNT OF TIME FOR THE RECALL REPAIR. THE MANUFACTURER WAS MADE AWARE OF THE ISSUE. THE CONTACT HAD NOT EXPERIENCED A FAILURE. QUEENS NY
Failure Date: 03/04/2015

13 10691960 2006 HONDA ACCORD Air Bags I STARTED MY ACCORD 2006 AND AIR BAG LIGHT IS ON. AFTER RE-STARTING ENGINE LIGHT DISAPPEAR FOR FEW SEC AND THEN IS BACK ON STEADY.
NEWTON NJ Failure Date: 02/23/2015

13 10672448 2006 HONDA ACCORD Air Bags TL* THE CONTACT OWNS A 2006 HONDA ACCORD. THE CONTACT RECEIVED NOTIFICATION OF NHTSA CAMPAIGN NUMBER: 14V351000 (AIR BAGS) HOWEVER, THE PART NEEDED TO DO THE REPAIR WAS UNAVAILABLE. THE CONTACT STATED THAT THE MANUFACTURER EXCEEDED A REASONABLE AMOUNT OF TIME FOR THE RECALL REPAIR. THE MANUFACTURER WAS MADE AWARE OF THE ISSUE. THE CONTACT HAD NOT EXPERIENCED A FAILURE. MERCEDITAS
PR Failure Date: 01/14/2015

NHTSA Consumer Complaints as of October 18, 2015

13 10695363 2006 HONDA ACCORD Air Bags 1.) EVERY TIME I TAP MY BRAKES IN AN ATTEMPT TO SLOW DOWN WHEN ON THE HIGHWAY, THE FRONT END OF THE CAR STARTS SHAKING. I HAD NEW TIRES PUT ON, THE BREAKS REPLACED AND HAD THE ROTORS CHECKED. I HAD A CHECK PERFORMED ON THE FRONT END AND THE MECHANIC SAYS THERE IS NOTHING WRONG WITH THE BRAKES, FRONT ALIGNMENT OR MY TIRES. 2.) THE CARS SHAKES WHEN I APPLY THE BREAKS WHEN SLOWING DOWN WHILE TRAVELING AT HIGH SPEED. I HAD THE SUSPENSION CHECKED AND NOTHING WAS NOTED OUT OF THE ORDINARY. 3.) WHEN I START THE CAR, THE AIRBAG LIGHT COMES ON STAYS ON. OTHER TIMES WHEN I START THE CAR. THE AIRBAG LIGHT COMES ON AND GOES OFF. ATLANTA GA

Failure Date: 01/07/2015

13 10664426 2006 HONDA ACCORD Air Bags TL* THE CONTACT OWNS A 2006 HONDA ACCORD. THE CONTACT RECEIVED NOTIFICATION OF NHTSA CAMPAIGN NUMBER: 14V351000 (AIR BAGS) HOWEVER, THE PART TO DO THE RECALL REPAIR WAS UNAVAILABLE. THE CONTACT STATED THAT THE MANUFACTURER EXCEEDED A REASONABLE AMOUNT OF TIME FOR THE RECALL REPAIR. THE MANUFACTURER WAS NOTIFIED OF THE ISSUE. THE CONTACT HAD NOT EXPERIENCED A FAILURE. MIAMI FL Failure Date: 12/15/2014

13 10664106 2006 HONDA ACCORD Air Bags I HAVE THE TAKATA AIRBAGS THAT ARE DEFECTIVE ACCORDING TO CONSUMERS MAGAZINE(JAN, 2015 ISSUE, PP.56-57. MY LOCAL HONDA DEALER, MULLER HONDA OF HIGHLAND PARK, INSIST THE CAR IS SAFE AND THE VEHICLE DOES NOT HAVE A DEFECTIVE BAG AND; THEREFORE, NOTHING NEEDS TO BE DONE FOR THE VEHICLE. I HAVE AN APPOINTMENT WITH THE DEALERSHIP SET FOR TUESDAY, 12/23/14 TO CHECK A LIGHT THAT IS LIT UP CONSTANTLY FOR THE AIRBAGS. THANK YOU FOR LOOKING INTO THIS. WARM REGARDS, JONATHAN M. KAMEN DEERFIELD IL Failure Date: 12/13/2014

13 10663890 2006 HONDA ACCORD Air Bags 2006 HONDA ACCORD. CONSUMER TRYING TO GET AIRBAGS FIXED DUE TO A RECENT

NHTSA Consumer Complaints as of October 18, 2015

RECALL. *TA WHEN THE CONSUMER ARRIVED AT THE DEALER, HE WAS INFORMED THERE WAS NO RECORD OF HIS APPOINTMENT AND THE PART WOULD HAVE TO BE ORDERED. *JB FALLS CHURCH VA Failure Date: 11/21/2014

13 10659347 2006 HONDA ACCORD Air Bags I WENT ON THE "RECALL.GOV" SITE AND IT WOULDN'T LET ME COMPLETE THE ENTRY PROCESS. IT KEPT SHOWING THESE WORDS TO COPY INTO A SPACE. I DID IT LIKE 10 TIMES AND WOULD NOT LET ME CONTINUE. THE SITE NEEDS HELP !!!! I HAVE A 2006 HONDA ACCORD AND WANTED TO KNOW ABOUT THE "AIR BAG" RECALL. PLEASE E-MAIL ME THE SOLUTION TO MY "RECALL.GOV" SITE ENTRY PROBLEM. [XXX] INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6). *TR TRUMBULL CT Failure Date: 11/19/2014

13 10653324 2006 HONDA ACCORD Air Bags 2006 HONDA ACCORD. THREE DAYS AFTER HAVING THE VEHICLE SERVICED, THE AIR BAG LIGHT ILLUMINATED AGAIN. *CW KAHULUI HI Failure Date: 11/03/2014

13 10650432 2006 HONDA ACCORD Air Bags TL* THE CONTACT OWNS A 2006 HONDA ACCORD. THE CONTACT STATED THAT SHE WAS INVOLVED IN A MINOR CRASH WHERE THE AIR BAGS DEPLOYED. THE SPECIFICS OF THE CRASH WERE NOT AVAILABLE AND A POLICE REPORT WAS NOT FILED. THE CONTACT SUSTAINED BURNS TO THE STOMACH DUE TO THE AIR BAG DEPLOYEMNT. THE VEHICLE WAS DESTROYED. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS UNKNOWN. THE VIN WAS UNAVAILABLE. OKLAHOMA CITY OK Failure Date: 10/27/2014

13 10650052 2006 HONDA ACCORD Air Bags AIRBAG WARNING LIGHT ON DASH IS ON AND WON'T GO OFF. HONDA DEALER STATES I MUST PAY \$125 TO HAVE IT TESTED. IF TEST SHOWS IT IS CAUSED BY SEAT BELT PROBLEM, COST WILL BE WAIVED, OTHERWISE I MUST PAY FOR BOTH THE

NHTSA Consumer Complaints as of October 18, 2015

DIAGNOSTIC TEST AND THE REPAIR. *TR AVONDALE AZ Failure Date:
10/20/2014

13 10723690 2006 HONDA ACCORD Air Bags TL* THE CONTACT
OWNS A 2006 HONDA ACCORD. THE CONTACT RECEIVED NOTIFICATION OF
NHTSA CAMPAIGN NUMBER: 14V351000 (AIR BAGS) AND STATED THAT THE
PART WAS NOT AVAILABLE TO SCHEDULE A RECALL REPAIR WITHIN A
REASONABLE TIMEFRAME. THE DEALER DID NOT GIVE A SPECIFIC DATE FOR
WHEN THE PART WOULD BECOME AVAILABLE. THE MANUFACTURER COULD
NOT PROVIDE AN ESTIMATED DATE FOR WHEN THE CONTACT'S VEHICLE
WOULD RECEIVE THE RECALL REPAIR. THE CONTACT HAD NOT EXPERIENCED
A FAILURE. MANHASSET HILLS NY Failure Date: 09/15/2014

13 10633559 2006 HONDA ACCORD Air Bags AIRBAG WARNING
LAMP ON DASHBOARD BEGAN TO LIGHT UP SPORADICALLY. LATER IN THE
MONTH THE CAR WAS TAKEN FOR ROUTINE MAINTENANCE AT A CERTIFIED
HONDA DEALER, IT WAS EXPLAINED THAT THERE IS A PROBLEM WITH THE
DRIVER SIDE AIRBAG AND THE LIGHT INDICATED A PROBLEM WHICH
PREVENTS THE MECHANICS FROM KNOWING IF THE AIRBAG WILL DEPLOY IN
THE EVENT OF AN ACCIDENT. THIS DEFECT IS ONLY COVERED FOR HONDA
ACCORD V6 MODELS 2001-2005 AND HAS A QUOTED REPAIR OF \$700-900.
*TR HAWTHORNE CA Failure Date: 09/01/2014

13 10632244 2006 HONDA ACCORD Air Bags TL* THE CONTACT
OWNS A 2006 HONDA ACCORD. THE CONTACT STATED THAT WHILE DRIVING AT
APPROXIMATELY 5 MPH, THE VEHICLE ACCELERATED AND THE AIR BAGS
DEPLOYED. THE VEHICLE WAS TAKEN TO AN INDEPENDENT MECHANIC FOR
DIAGNOSIS. THE MECHANIC WAS UNABLE TO LOCATE A FAILURE. THE VEHICLE
WAS NOT REPAIRED. THE MANUFACTURER WAS NOT NOTIFIED OF THE
FAILURE. THE APPROXIMATE FAILURE MILEAGE WAS 36,000. UPDATED
10/24/2014*LJ UPDATED 4/17/15 *JS FOLEY AL Failure Date:
08/11/2014

NHTSA Consumer Complaints as of October 18, 2015

13 10625678 2006 HONDA ACCORD Air Bags 2006 HONDA
ACCORD. CONSUMER WRITES IN REGARDS TO VEHICLE AIRBAG ISSUES.
*SMD THE CONSUMER WAS INFORMED, THE AIR BAG ISSUE, DID NOT
INCLUDED HIS MODEL, BECAUSE IT WAS NOT REGISTERED OR FIRST SOLD IN
ONE OF THE HUMIDITY STATES. *JB LAKE ORION MI Failure Date:
08/01/2014

13 10610320 2006 HONDA ACCORD Air Bags TL* THE CONTACT
OWNS A 2006 HONDA ACCORD. WHILE DRIVING APPROXIMATELY 35 MPH, THE
PASSENGER SIDE AIR BAG DEPLOYED WITHOUT WARNING. THE VEHICLE WAS
NOT DIAGNOSED OR REPAIRED. THE MANUFACTURER WAS NOT NOTIFIED. THE
APPROXIMATE FAILURE MILEAGE WAS 124,000. JCC GENESEO
NY Failure Date: 07/13/2014

13 10611300 2006 HONDA ACCORD Air Bags DEAR SIR OR
MADAM, THE AIR BAGS (DRIVER AND PASSENGER SIDE) DEPLOYED ON MY
2006 HONDA ACCORD AT LESS THAN 10MPH WITH MY SEAT BELTS ON
RESULTING IN SCRATCHES ON MY LEFT FRONT BUMPER (NO OTHER VISIBLE
HARD IMPACT DAMAGE). THIS INCIDENT OCCURRED WHILE PERFORMING A
SLOW TURN INTO A PARKING LOT SPOT. I HAD CONTACTED BOTH HONDA USA
AND MY LOCAL DEALERSHIP EXPRESSING MY CONCERN THAT ONCE
REPAIRED, THE AIR BAGS COULD AGAIN UNINTENTIONAL DEPLOY WHILE
DRIVING THE CAR. HONDA USA ASKED ME TO TAKE CAR TO LOCAL HONDA
DEALER FOR INSPECTION AND EVALUATION. I BROUGHT MY CAR AT HONDA
DEALER BUT THEY SAID THEY WERE NOT EQUIPPED WITH SKILL AND TOOLS
TO INSPECT AND EVALUATE AND STATED THAT I SHOULD GO TO A THIRD
PARTY COLLISION SHOP. I CONTACTED HONDA USA AGAIN AND THEY ASKED
ME TO GO TO MY INSURANCE COMPANY TO DETERMINE IF A DEFECT IS
PRESENT. I BELIEVE THOSE ARE UNACCEPTABLE AND SURPRISING
SUGGESTIONS. IT IS MY BELIEVE THAT HONDA HAS A MAJOR DEFECT IN THE
AIR BAG SENSOR AND DOES NOT WISH TO INVESTIGATE AND/OR ACKNO
WLEDGE CULPABILITY IN A DEFECTIVE SAFETY COMPONENT.

NHTSA Consumer Complaints as of October 18, 2015

REQUESTING TO ADVISE ME ON HOW SHOULD I PROCEED. *TR

COLLIERVILLE TN Failure Date: 07/04/2014

13 10704600 2006 HONDA ACCORD Air Bags TL* THE CONTACT OWNS A 2006 HONDA ACCORD. THE CONTACT STATED THAT THE RECALL NOTICE FOR NHTSA CAMPAIGN NUMBER: 14V351000(AIR BAGS) WAS RECEIVED IN APRIL OF 2014. AFTER CONTACTING THE DEALER AND THE MANUFACTURER ON MULTIPLE OCCASIONS, THE CONTACT WAS INFORMED THAT THE PARTS NEEDED TO REPAIR THE VEHICLE WERE STILL NOT AVAILABLE AND NO ESTIMATED TIME FOR RECEIVING THE PARTS COULD BE GIVEN. THE CONTACT HAD NOT EXPERIENCED A FAILURE. MOUNTAIN VIEW CA Failure Date: 04/01/2014

13 10566699 2006 HONDA ACCORD Air Bags ON THE MORNING OF 1/28/2013 AT APPROXIMATELY 7:30AM CST, I WALKED OUT TO MY CAR TO START IT. WHEN I TURNED THE KEY, THE PASSENGER SIDE CURTAIN AIR BAGS DEPLOYED. SINCE IT WAS -12F OUTSIDE, I FIGURED THERE WAS SOME SORT OF MECHANICAL FAILURE AND HONDA WOULD COVER IT. I CALLED HONDA OF LISLE, IL AND THEY ASKED THAT I BRING IT IN FOR DIAGNOSTICS. I DROPPED THE CAR OFF THURSDAY MORNING AND LATER THEY CALLED AND SAID THEY FOUND SCRAPES UNDER THE CAR AND THAT THE COMPUTER RETURNED SRS CODES THAT INDICATED A COLLISION TOOK PLACE. I TOLD THEM THAT THERE HAVE ONLY BEEN TWO INCIDENTS WITH THE CAR, NEITHER OF WHICH REQUIRED ANY BODY WORK. WE RAN OVER A VERY DEEP POTHOLE IN 2006, WHICH REQUIRED THE RIM TO BE REPLACED. IN 2007 (OR POSSIBLY 08), I FELL INTO THE REAR PASSENGER SIDE QUARTER PANEL WHILE ATTEMPTING TO ROLLER BLADE FOR THE FIRST TIME AND DENTED IT. BECAUSE THE SCRAPES THAT HE DESCRIBED SEEM TO HAVE BEEN IN THE EXACT SAME AREA AS WHERE WE HIT THE POTHOLE, I FIGURED THEY MUST HAVE COME FROM THAT. THEY TOLD ME THEIR ZONE MANAGER FROM HONDA AMERICA NEEDED TO INVESTIGATE THE ISSUE FURTHER AND WOULD BE IN THE NEXT DAY (FRIDAY) AND THAT THEY WOULD CONTACT ME WITH THE RESULTS. ON FRIDAY, I SPOKE TO MY SERVICE ADVISOR AND HE INFORMED ME THAT THE ZONE MANAGER

NHTSA Consumer Complaints as of October 18, 2015

DENIED MY CLAIM DUE TO HIS BELIEF THAT A COLLISION HAD TAKEN PLACE AND BECAUSE MY CAR IS OUT OF WARRANTY. ON MONDAY, 2/3/2013, I CALLED HONDA OF LISLE AGAIN AND SPOKE WITH THE GENERAL SERVICE MANAGER, [XXX] . AFTER EXPLAINING MY SITUATION TO HIM, HE SAID THERE IS NOTHING HE CAN DO AND THAT COVERING THE EXPENSE IS UP TO THE DISCRETION OF THE ZONE MANAGER. I THEN CALLED HONDA CORPORATE, ONLY AGAIN TO BE DENIED, GIVEN THE SAME REASON. I AM NOW STUCK WITH A CAR WITH DEPLOYED AIRBAGS THAT ARE GOING TO COST OVER \$2,000 TO REPAIR. INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6). *TR WHEATON IL Failure Date: 01/28/2014

13 10650271 2006 HONDA ACCORD Air Bags TL* THE CONTACT OWNED A 2006 HONDA ACCORD. WHILE DRIVING AT AN UNKNOWN SPEED DURING INCLEMENT WEATHER, THE CONTACT LOST CONTROL OF THE VEHICLE AND CRASHED INTO A GUARDRAIL SEVERAL TIMES. THE DRIVER AND PASSENGER FRONTAL AIR BAGS FAILED TO DEPLOY. A POLICE REPORT WAS FILED. THE CONTACT SUSTAINED INJURIES TO THE CHEST, HEAD, AND ELBOW. THE FRONT PASSENGER SUSTAINED BACK AND NECK INJURIES. THE REAR DRIVER SIDE PASSENGER SUSTAINED INJURIES TO THE FACE AND HEAD. THE OTHER REAR PASSENGER SUSTAINED INJURIES TO THE NECK AND WAIST. THE DRIVER AND BOTH REAR PASSENGERS REQUIRED MEDICAL ATTENTION. THE MANUFACTURER WAS MADE AWARE OF THE FAILURE. THE VEHICLE WAS DESTROYED. THE APPROXIMATE FAILURE MILEAGE WAS 70,000. UPDATED 12/09/14*LJ SPRINGFILED MA Failure Date: 01/01/2014

13 10662143 2006 HONDA ACCORD Air Bags TL* THE CONTACT OWNS A 2006 HONDA ACCORD. THE CONTACT STATED THAT NHTSA CAMPAIGN NUMBER: 14V351000 (AIR BAGS) HAD EXCEEDED A REASONABLE AMOUNT OF TIME FOR REPAIR. THE MANUFACTURER STATED THEY WOULD CALL THE CONTACT BACK AND SET UP AN APPOINTMENT. HOWEVER A CALL WAS NOT RETURNED. THE VEHICLE WAS NOT REPAIRED. THE CONTACT HAD NOT EXPERIENCED THE FAILURE. AUGUSTA GA Failure Date: 12/28/2013

NHTSA Consumer Complaints as of October 18, 2015

13 10733765 2006 HONDA ACCORD Air Bags I WAS DRIVING OUT OF MY NEIGHBOOD IN A 25 MPH ZONE AND HIT A MAIL TRUCK ON THE WRONG SIDE IF THE ROAD. I HIT THE MAIL TRUCK AFTER TURNING A CORNER, AS I TURNED THE CORNER, A SPIDER CRAWLED FROM THE CEILING OF MY CAR AND I TRIED TO SWAT IT AWAY AND DIDN'T SEE THE MAIL TRUCK. THE IMPACT CAUSED THE AIRBAG TO DEPLOY BUT THE DEPLOYMENT OF THE AIRBAG WAS DELAYED, IT DID NOT HAPPENED IMMEDIATELY BUT A FEW SECONDS AFTER THE IMPACT CAUSING BAD BURNS AND BLISTERS TO MY HAND. I DID NOT SEEK MEDICAL ATTENTION BUT DOCTORED ON MY HAND MYSELF; IT TOOK MONTHS BEFORE THE APPEARANCE IF MY HAND WOULD LOOK NORMAL. I HAVE PICTURES. THE REPAIR SHOP, TOW TRUCK AND POLICE OFFICER COULD NOT UNDERSTAND WHY THE AIRBAG DEPLOYED IN THE FIRST PLACE WITH SUCH LOW SPEED. IT TOOK MONTHS TO GET MY CAR REPAIRED, LONGER THAN NORMAL. I AM THE ORIGINAL OWNER OF THE CAR. THE RECENT RECALLS HAVE CAUSED ME TO WRITE THIS, I HAD NO IDEA THE AIRBAGS WERE DEFECTIVE. IT WAS A VERY BIG INCONVIENIENCE TO ME.

NEWPORT NEWS VA Failure Date: 07/06/2013

13 10500764 2006 HONDA ACCORD Air Bags MY CAR CRASHED INTO SEVERAL WOODEN POSTS WHERE THE ENTIRE FRONT END WAS DAMAGED INCLUDING THE FRAME AND MY AIR BAGS NEVER DEPLOYED. *TR FORT WORTH TX Failure Date: 01/01/2013

13 10500771 2006 HONDA ACCORD Air Bags MY CAR CRASHED INTO SEVERAL WOODEN POSTS WHERE THE ENTIRE FRONT END WAS DAMAGED INCLUDING THE FRAME AND MY AIR BAGS NEVER DEPLOYED. THE CAR WAS TOTALED AND I SUFFERED INJURIES WHICH REQUIRED MEDICAL TREATMENT. I INFORMED AMERICAN HONDA OF THIS ISSUE ON 2 SEPERATE OCCASIONS AND NOT ONCE DID THEY MENTION ABOUT LOOKING INTO A POSSIBLE DEFECT IN THEIR VEHICLE. *TR FORT WORTH TX Failure Date: 01/01/2013

13 10492058 2006 HONDA ACCORD Air Bags MY HUSBAND WAS ON HIS WAY HOME WHEN HIS LEFT TURN LIGHT TURNED GREEN. A LADY

NHTSA Consumer Complaints as of October 18, 2015

RAN THE RED LIGHT AND T-BONED OUR CAR. THE CAR IS TOTALED. MY HUSBAND SUFFERED INJURIES, WAS KNOCKED OUT AND HAS CONCUSSION. NOT ONE OF THE AIR BAGS WENT OFF AND OUR CAR WAS LOADED WITH BAGS IN FRONT AND BACK SEATS. IT IS THE REASON WHY WE PURCHASED THE CAR. WE CALLED "HONDA AMERICA" AND ALL THEY DID WAS LISTEN AND TOLD US TO CONTACT OUR DEALER WHERE WE PURCHASED THE CAR TO HAVE THEM LOOK AT IT. THE DEALER LAUGHED AND TOLD US THEY HAVE NOTHING TO DO WITH THE MANUFACTURING OF THE CAR. HONDA AMERICA TOLD US TO ALSO HAVE OUR INSURANCE COMPANY FIGURE OUT WHEN HAPPENED. WE TALKED TO OUR INSURANCE COMPANY AND THEY SAID THEY COULD WRAP THE HONDA AND SEND IT TO HONDA AMERICA, "BUT" HONDA AMERICA SAID THEY DON'T HAVE A PLACE FOR THE HONDA TO BE LOOKED AT. "HONDA AMERICA" NEEDS TO TAKE RESPONSIBILITY!!!! CALLED AN ACCIDENT ATTORNEY TO DEAL WITH HONDA AMERICA. *TR BEAVERTON

OR Failure Date: 12/28/2012

13 10492952 2006 HONDA ACCORD Air Bags TL* THE CONTACT OWNS A 2006 HONDA ACCORD. THE CONTACT STATED THAT WHILE DRIVING 10 MPH, ANOTHER VEHICLE CRASHED INTO THE DRIVER'S SIDE OF HER VEHICLE. UPON IMPACT, THE AIR BAGS FAILED TO DEPLOY. THE VEHICLE WAS COMPLETELY DESTROYED AND THE DRIVER SUSTAINED INJURIES TO THE HEAD AND SPINE. BOTH THE MANUFACTURER AND DEALER WERE CONTACTED BUT NEITHER PROVIDED ANY ASSISTANCE. THE FAILURE MILEAGE WAS 82,000. UPDATED 10/29/13*LJ BEAVERTON OR Failure Date: 12/26/2012

13 10493694 2006 HONDA ACCORD Air Bags AIRBAG LIGHT STAYED ON WITHOUT ACCIDENT. I BROUGHT IT TO DEALERSHIP AND THEY DID A DIAGNOSTIC SCAN. THE GUY SAID DRIVER POSITION SENSOR HARNESS IS BROKEN. I RESEARCHED THIS PROBLEM AND ITS LOOK LIKE THIS A COMMON PROBLEM WITH HONDA. I CALLED HONDA AND THEY SAID THE VIN IS NOT INCLUDED IN THE RECALL. HONDA MUST BE INCREASE THE SCOPE OF THE RECALL!!! *TR SILVERDALE WA Failure Date: 12/17/2012

NHTSA Consumer Complaints as of October 18, 2015

13 10487361 2006 HONDA ACCORD Air Bags MY SRS LIGHT INDICATING A MALFUNCTIONING OF THE FRONT AIRBAGS CAME UP JUST WHEN I CLOSED THE DASHBOARD CABIN. WHEN REPORTED THIS TO HONDA DEALER THEY SAY IT IS NOT COVERED UNDER WARRANTY AND THEY DON'T KNOW HOW IT CAME UP AS THIS LIGHT SHOULD ONLY TURN ON IN CASE OF ACCIDENT. NOW THEY WANT ME TO PAY \$1100 - \$1200 TO REPLACE THE WHOLE SRS UNIT. PLEASE SUGGEST. *TR HERNDON VA

Failure Date: 11/01/2012

13 10596735 2006 HONDA ACCORD Air Bags TL* THE CONTACT OWNED A 2006 HONDA ACCORD. THE CONTACT STATED THAT WHILE THE DRIVER WAS TRAVELING 40 MPH, SHE WAS INVOLVED IN A CRASH WHERE ONLY ONE AIR BAG DEPLOYED. A POLICE REPORT WAS FILED AND THE DRIVER SUSTAINED INJURIES. THE VEHICLE WAS DESTROYED. THE MANUFACTURER WAS MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS 63,000. UPDATED 08/11/14*LJ ROMNEY WV Failure Date: 11/01/2012

13 10660691 2006 HONDA ACCORD Air Bags I WAS INVOLVED IN AN ACCIDENT AND MY AIRBAGS NEVER DEPLOYED. A POLICE REPORT WAS FILED AND THE OTHER CAR GOT TICKETED. I WAS DRIVING DOWN THE ROAD AND A CAR PULLED IN FRONT OF ME AND I T-BONED THEM. NOT SURE WHY MY AIRBAGS DIDN'T DEPLOY. ALSO, SINCE 2012 AS I ACCELERATE AND PRESS THE GAS PEDAL MY CAR SHUDDERS, LIKE ITS SKIPPING. NOT SURE WHY BUT IT'S NOT RIGHT AND SHOULDN'T DO THIS. SANFORD NC Failure Date: 10/26/2012

13 10468104 2006 HONDA ACCORD Air Bags WE WERE STOPPED AT A STOP LIGHT WAITING FOR THE LIGHT TO CHANGE. OUR CAR WAS COMPLETELY STOPPED FOR 30+ SECONDS WHEN BOTH FRONT AIR BAGS SUDDENLY DEPLOYED. THE CAR WAS NOT HIT AND THERE WAS NO OTHER CAR WITHIN 10 FEET. WHEN WE GOT OUT OF THE CAR, BOTH AIR BAGS EXPLODED AGAIN. *TR SUNNYVALECA Failure Date: 07/28/2012

NHTSA Consumer Complaints as of October 18, 2015

13 10468240 2006 HONDA ACCORD Air Bags AIRBAG LIGHT
WENT ON. REPLACEMENT OF DRIVERS SEAT POSITION SENSOR NEEDED.
PARTS FROM HONDA \$700 PLUS LABOR. NO WATER LOCATED NEAR SEAT AT
TIME OF LIGHT ACTIVATION. NO ELECTRONICS NEAR SEAT AT TIME OF LIGHT
ACTIVATION. *TR WINCHESTER VA Failure Date: 07/16/2012

13 10452501 2006 HONDA ACCORD Air Bags I FILLED UP MY
CAR AT THE HESS STATION ON ROUTE 112 IN CORAM , LONG ISLAND, NEW
YORK. I PUT MY CAR , SLOWLY IN REVERSE AND THE CAR TOOK OFF LIKE IT
HAD A MIND OF IT'S OWN. I STEPPED ON THE BRAKE, BUT NOTHING
HAPPENED AND THE CAR CONTINUED TO SPEED UP IN REVERSE- WITH MY
FOOT ON THE BRAKE - HEADING TOWARDS A VAN WITH A BABY IN IT IN A CAR
SEAT. I QUICKLY PUT THE CAR IN FORWARD, AND WITH MY FOOT STILL ON THE
BRAKE, THE CAR FLEW ACROSS THE PARKING LOT OF THE GAS STATION,
CROSSED TWO LANES OF TRAFFIC, CRASHED INTO THE WOODS. I STEERED
AWAY FROM A TELEPHONE POLE I WAS DEFINITELY GOING TO HIT AND, WHEN I
WENT INTO THE WOODS THE AIR BAG WENT OFF AND COVERED MY FACE. I
THEN WENT BACK ACROSS TWO LANES OF TRAFFIC AGAIN, WITH THE AIRBAG
OVER MY FACE, AND CRASHED INTO THE CURB IN FRONT OF THE HESS
STATION WHEN I REPORTED THE ACCIDENT TO MY INSURANCE COMPANY, THE
HARTFORD, I ASKED THEM TO CHECK OUT THE SPEED SENSOR- . MY
INSURANCE COMPANY SAID THEY WOULD NOT BE ABLE TO CHECK OUT THE
SPEED SENSOR. I THEN CALLED HONDA CUSTOMER SERVICE AND TOLD
THEM OF THE INCIDENT. THEY INFORMED ME THAT, UNLESS THEY RECEIVED A
REQUEST FROM THE HARTFORD, THEY WOULD NOT CHECK OUT THE SPEED
SENSOR. I THEN CALLED THE HARTFORD AND REQUESTED THAT THEY CALL
HONDA TO HAVE THE CAR INSPECTED BY HONDA THEMSELVES. HARTFORD
TOLD ME THAT THEY WOULD NOT PAY TO HAVE HONDA INSPECT THE VEHICLE
- THEY WERE JUST GOING TO HAVE THEIR ADJUSTER LOOK AT THE CAR AND
TOLD ME THEY WERE NOT GOING TO LOOK AT THE SPEED SENSOR AT ALL.
SO , BASICALLY, NO ONE IS WILLING TO DO ANYTHING AND I ALMOST KILLED A
BABY IN A CAR SEAT AND MYSELF THIS SEEMS LUDICROUS TO ME THAT NO
ONE IS EVEN WILLING TO CHECK THIS DEFECT OUT. I SINCERELY HOPE

NHTSA Consumer Complaints as of October 18, 2015

THAT YOU CAN HELP ME WITH THIS VERY DIFFICULT SITUATION. *TR

*JS CENTER MORICHES NY Failure Date: 03/12/2012

13 10448154 2006 HONDA ACCORD Air Bags TL* THE CONTACT OWNS A 2006 HONDA ACCORD. THE CONTACT STATED THAT THE AIR BAG WARNING LIGHT ILLUMINATED ON THE INSTRUMENT PANEL OF THE VEHICLE. THE DEALER DIAGNOSED THAT THE DRIVER SEAT POSITION SENSOR NEEDED TO BE REPLACED. THE DEALER AND THE MANUFACTURER WAS NOTIFIED OF THE FAILURE, BUT ADVISED THE CONTACT THAT THE VEHICLE WAS NOT INCLUDED IN NHTSA CAMPAIGN ID NUMBER: 07V001000 (AIR BAGS:FRONTAL:SENSOR/CONTROL MODULE). THE VEHICLE WAS NOT REPAIRED. THE FAILURE AND CURRENT MILEAGE WAS APPROXIMATELY 110,000. OKLAHOMA CITY OK Failure Date: 02/02/2012

13 10389852 2006 HONDA ACCORD Air Bags TL*THE CONTACT OWNS A 2006 HONDA ACCORD. THE CONTACT STATED THAT THE SAFETY RESTRAINT SYSTEM LAMP ILLUMINATED. THE VEHICLE WAS TAKEN TO THE DEALER WHO CONFIRMED THAT THE CABLE TO THE DRIVERS SEAT POSITION CENTER WAS TORN DUE TO THE SEAT BEING MOVED BACK AND FORTH. THE MANUFACTURER WAS CONTACTED AND OFFERED NO ASSISTANCE SINCE THE RECALL NHTSA CAMPAIGN ID NUMBER: 07V001000 (AIR BAGS:FRONTAL:SENSOR/CONTROL MODULE) AND WAS ONLY A PART OF 2004-2005 MODEL VEHICLE. THE VEHICLE WAS REPAIRED. THE FAILURE AND CURRENT MILEAGE WAS 95,000. UPDATED 4/11/2011 *CN UPDATED 08/03/11 MIDDLETOWN NJ Failure Date: 01/01/2011

13 10327717 2006 HONDA ACCORD Air Bags TL* THE CONTACT OWNS A 2006 HONDA ACCORD. WHILE DRIVING AT SPEEDS OF 35 MPH, THE AIR BAGS DEPLOYED WITHOUT WARRANT. THE CONTACT WAS ABLE TO MOVE THE VEHICLE FROM THE HIGHWAY WITHOUT INCIDENT AND WAS ASSISTED BY A PASSING POLICE OFFICER WHO FILED A POLICE REPORT. THE DEALER WAS UNABLE TO DIAGNOSE THE FAILURE AND ADVISED THE AIR BAGS MAY HAVE DEPLOYED DUE TO ABNORMALLY PRESSURE. THE MANUFACTURE WOULD NOT PROVIDE ANY ASSISTANCE WITH REPAIRS TO THE AIR BAGS. THE

NHTSA Consumer Complaints as of October 18, 2015

APPROXIMATE FAILURE MILEAGE WAS 115,000 AND THE CURRENT MILEAGE WAS 120,712. SHUQUALAK MS Failure Date: 02/26/2010

13 10263138 2006 HONDA ACCORD Air Bags WAS DRIVING MY 2006 HONDA ACCORD EX SEDAN ON THE HIGHWAY AND THE DRIVER-SIDE CURTAIN AND SEAT AIRBAGS DEPLOYED WITHOUT INCIDENT. THERE WAS NO ACCIDENT OR IMPACT OF ANY KIND. THE AIRBAGS JUST DEPLOYED. LIKEWISE, THE DRIVER'S SEAT BELT TIGHTENED AND WILL NOT PULL OR RETRACT. LUCKILY I WAS ABLE TO KEEP THE CAR UNDER CONTROL AND NOT WRECK, DESPITE BEING CAUGHT OFF GUARD. NOTHING WAS DONE TO CORRECT THIS FAILURE. HONDA INDICATED THAT THERE ARE NO RECALLS AND THEY ARE UNAWARE OF ANY RELATED ISSUES. HONDA SUGGESTED I CALL MY INSURANCE WHO TOLD ME THAT IT WAS A MECHANICAL FAILURE AND THEREFORE NOT COVERED. *TR JOHNSTOWN PA Failure Date: 03/26/2009

13 10261146 2006 HONDA ACCORD Air Bags I WAS IN A HEAD-ON COLLISION THAT TOTALED MY CAR. THE AIRBAGS DID NOT DEPLOY, CAUSING MY HEAD TO HIT THE CAR. IT WAS A 2006 HONDA ACCORD THAT I BOUGHT NEW. *TR AFTON OK Failure Date: 03/05/2009

13 10256430 2006 HONDA ACCORD Air Bags TL*THE CONTACT OWNS A 2006 HONDA ACCORD. THE DRIVER SIDE AIR BAG SENSOR LIGHT REMAINED ILLUMINATED AND FAILED TO SHUT OFF. THE LIGHT ALSO REMAINED ILLUMINATED AFTER THE DEALER RESET IT. THE FAILURE OCCURRED AFTER 100,000 MILES. THE FAILURE WAS DIAGNOSED AND THE SENSOR WAS RESET ON THREE OCCASIONS; HOWEVER, WITHIN THREE DAYS THE AIR BAG SENSOR LIGHT CAME BACK ON. THE CURRENT AND FAILURE MILEAGES WERE 106,000. LAKE WOOD NJ Failure Date: 01/17/2009

13 10227460 2006 HONDA ACCORD Air Bags TL*THE CONTACT OWNS A 2006 HONDA ACCORD. WHILE DRIVING 50 MPH, THE CONTACT MADE AN INCORRECT TURN AND STRUCK A PALM TREE WITH THE FRONT END OF

NHTSA Consumer Complaints as of October 18, 2015

THE VEHICLE. DURING THE CRASH, THE SAFETY HARNESS RETRACTOR FAILED AND THE AIR BAGS DID NOT DEPLOY. THERE WERE NO INJURIES AND A POLICE REPORT WAS FILED. THE VEHICLE WAS TOWED TO A JUNKYARD AND HAS NOT BEEN DIAGNOSED BY THE DEALER. THE CURRENT AND FAILURE MILEAGES WERE 24,000. PALM HARBOR FL Failure Date: 05/09/2008

13 10214574 2006 HONDA ACCORD Air Bags AIR BAG FAILURE DURING CRASH OF 2006 HONDA ACCORD EX, VEHICLE ACCIDENT BETWEEN TWO CARS, ANOTHER VEHICLE PULLED INTO MAIN TRAFFIC MY HONDA STRUCK SAID VEHICLE IN REAR QUARTER, HONDA THEN SPUN OFF INTO GUARD RAIL STRIKING LEFT FRONT SIDE. BOTH SIDE OF HONDA CRUSDED GEICO HAS TOTALED THE HONDA, THIS WAS AT 55 MPH AIR BAGS DID NOT DEPLOY. GEICO HAS HONDA AT BRANDYWINE SALVAGE, PG, MD. *TR OWINGS MD Failure Date: 01/07/2008

13 10208074 2006 HONDA ACCORD Air Bags DRIVING MY 2006 HONDA ACCORD AT 55 MPH PASSENGER SIDE CURTAIN AIRBAG DEPLOYED FOR NO REASON HONDA DEALER CAN FIND NO REASON FOR DEPLOYMENT. TERRIFYING EXPERIENCE. *TR NORWALK 06851 CT Failure Date: 10/18/2007

13 10196785 2006 HONDA ACCORD Air Bags I WAS IN A HIGH SPEED MOTOR VEHICLE CRASH ALONG WITH A COWORKER THAT I CAR POOL WITH IN THE 2006 ACCORD WHEN A DOG RAN OUT IN FRONT OF THE CAR AT 4:30 AM ON THE HIGHWAY ON MY WAY TO WORK. I WAS TRAVELING AT APPROXIMATELY 70-75 MPH, BRAKED AND SWERVED, BUT STILL HIT THE DOG AT HIGH SPEED. THE DOG WAS OF MEDIUM TO LARGE SIZE APPROXIMATELY 60-70 LBS AND CAUSED CONSIDERABLE DAMAGE TO THE FRONT BUMPER. I THEN LOST CONTROL OF THE CAR, WENT OF THE ROAD, AND THE VEHICLE ROLLED AT LEAST 3 TIMES. THE VEHICLE SUSTAINED A GREAT AMOUNT OF DAMAGE TO THE FRONT BUMPER AS WELL AS TO THE ENTIRE PASSENGER SIDE OF THE CAR, YET NO AIRBAGS DEPLOYED. I WAS TOLD BY MY HONDA DEALERSHIP THAT "THE SENSORS FOR THE AIRBAGS WERE VERY SMALL AND

NHTSA Consumer Complaints as of October 18, 2015

MUST BE HIT DIRECTLY IN ORDER FOR THE AIRBAGS TO DEPLOY, SO THE SENSORS MUST NOT HAVE BEEN HIT JUST RIGHT , AND THERE WAS PROBABLY NO REASON TO BE CONCERNED. HOWEVER, ANYONE WHO SAW THE DAMAGE TO MY CAR, INCLUDING STATE TROOPERS, EMS, TOW TRUCK DRIVERS, AS WELL AS FAMILY AND FRIENDS, ALL STATED THAT THE AIRBAGS SHOULD HAVE DEPLOYED IN THIS INSTANCE. I DID NOT FIND THAT THESE AIRBAGS TO BE VERY BENEFICIAL IF WHAT THE PERSON AT THE HONDA DEALERSHIP SAID WAS TRUE. BOTH MY PASSENGER AND I SUFFERED WHIPLASH, BACK AND NECK STRAIN, AND MILD CONCUSSIONS, THANKFULLY THAT WAS ALL. HOWEVER I COULD NOT HELP BUT WONDER IF THE AIRBAGS WOULD HAVE SAVED US FROM THE INJURIES WE DID SUSTAIN. THE CAR WAS TOTALED BY INSURANCE COMPANY . THEREFORE, NO REPAIRS HAVE BEEN DONE. I AM DEBATING WHETHER TO FILE A COMPLAINT WITH HONDA REGARDING A POSSIBLE DEFECT IN AIRBAG SENSORS.*AK TOLEDO

OH Failure Date: 07/11/2007

13 10183349 2006 HONDA ACCORD Air Bags I PURCHASED A NEW 2006 HONDA ACCORD 4 DOOR EX-V6 IN DEC. 2005 VIN-[XXX]. ON 2-20-2007 I WAS INVOLVED IN A FRONTAL COLLISION WITH ANOTHER CAR, I SUSTAINED DAMAGED FRONT BUMPER, HOOD, DRIVER'S SIDE FENDER, RADIATOR. THE PROBLEM IS THAT MY AIR BAGS FAILED TO DEPLOY. BOTH MYSELF AND MY PASSENGER WERE WEARING SEAT & SHOULDER BELTS AND WERE NOT HURT. THIS VEHICLE HAD NEVER BEEN IN AN ACCIDENT BEFORE THE ACCIDENT ON 2-20-2007. I'M REPORTING DEFECTIVE AIR BAGS. *NM UPDATED 07/11/2012

*JS INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6) ROYAL OAKS

CA Failure Date: 02/20/2007

13 10681468 2006 HONDA ACCORD Air Bags LOOK AT MY AIRBAGS PLS FAIRFAX CA Failure Date: 08/01/2006

13 10167146 2006 HONDA ACCORD Air Bags LOW SPEED PARKING LOT ACCIDENT, AIR BAG DEPLOYED. PROPELLANT WAS NOT

NHTSA Consumer Complaints as of October 18, 2015

PROPERLY VENTED AND CAUSED 2ND DEGREE BURNS FROM THE THUMB TO
THE ELBOW. **NM AUSTIN TX Failure Date: 07/22/2006

13 10160936 2006 HONDA ACCORD Air Bags DT*: THE
CONTACT STATED THAT WHILE DRIVING DOWN A RAMP THE AIRBAG ON THE
PASSENGER SIDE DEPLOYED WITHOUT CAUSE. THERE WAS NO PRE-
INCIDENT BRAKING AND THE AIRBAG WARNING LIGHT DID NOT ILLUMINATE.
THERE WAS NO POLICE REPORT FILED, PICTURES TAKEN OR REPAIR
INVOICES AVAILABLE. THE DEALERSHIP RETAINED THE VEHICLE FOR 7 WEEKS
AND COULD NOT DETERMINE THE PROBLEM HOWEVER THE CEILING, AIRBAG,
AND THE SEAT WERE REPLACED. COGAN STATION PA Failure Date:
01/12/2006